



Exploded

H3024 Glute Isolator



please note :parts didn't demolitionde part
and fast eners not listide on the introduction

C16	Cushion	1
C2	Flat washer $\phi 8$	6
C1	Cap head inner hex screw $\phi 8 \times 35$	6
B	配重组	1
A34	Socket cap inner hex M10*16	1
A33	Cover B020	1
A20	Gasket D0003	6
A19	Spring washer $\phi 12$	6
A18	Screw cap S208	6
A17	Outer hex screw M12*35	6
A6	Cup head inner hex screw M6*15	8
A5	Cup head cross tapping screw S13*89	4
A3	Top cover	1
A2	Back shroud	1
A1	Front shroud	1
ZD	Elbow cushion	1
T06	Support sets	1
01	Door frame	1
T03	Main frame	1
T02	Movable arm	1
T01	Cushion adjustment	1
Number	Name	quantity